Under Review Notification

Raised By: Vanessa Morel Product #: RBA9983

Date: 2019.10.29 Product Name: TORQUE ADAPTER

		"Y" or "N" Required for Each Part							t		
	1	Do not leave blank									
Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143) (eg. RBEM324U3010101-1)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	DO NOT SHIP	Red Tag/Quarantine Stock	Advise Customers	Hold all Production	Quarantine Tooling (Jigs, Fixtures, etc.)	Re-Work Stock	IPP Under Review (Enginer Signoff Required.)	Put Product Specifications Under Review ("Bluefiles")	Reserved ECN / URF Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
RBA9983	RBA9983 Rev	Υ	Υ	Ν	Υ	Υ	Ν	Ν	Ν	19-1081	See below

Description of Issue:

Issues stated on ADR (Manufacturing, Drawing is wrong)

RBA9983 must be put on HOLD in Plex

RBA9983 Finish good stock must be put in quarantine

No new manufacturing is permitted until Engineering release new Rev

Can remain on website with a note to contact sales for a quote. They must NOT be able to put the tool into cart

'P" Part must be put on HOLD in Plex as well

Distribution: VP Operations Director of Engineering Customer Support Manager Technical Support

Director of Operations

Chief Engineer

Customer Support Manager

Product Manager - Solutions Provider

Director Quality Assurance Engineering Project Managers Production Planners Supply Chain Director / Senior Buyer

QC Coordinator Engineering Clerk Purchasing Manager Marketing Eugene